Copy X of 11

25X

19 September 1967

MEMORANDUM FOR:

Director of Special Activities

SUBJECT:

OXCART Program Areas Requiring a

1 October 1967 Decision

This memorandum is for information only. l.

2. Personnel

No replacements are presently in the "pipeline" for Agency, Military or Contractor personnel assigned to this program. The normal lead time for Agency and Military replacements is one year. These two categories are not as critical as the various contractor areas, as it is conceivable that the people on-board could be "frozen" until suitable replacements are obtained. closed is a chart showing the number of military personnel whose tours are scheduled to expire during FY-68. its T/O military strength was

25X

at the end of FY-67.

The personnel area of prime concern at this point in time is the Contractor complement. In theory, and on deployment the contract personnel know that BLACK SHIELD will be terminated on 30 November, but not that the program is to be phased out. It would be naive to believe that word of the NRO decision to cancel the program has not filtered through. With this information in hand and possessing a high survival I. Q., it is felt that the technical people will be leaving the program as soon as they can make new arrangements. Evidence that this is presently happening is described in the following report from the Headquarters' Avionics This is followed by an analysis of the security problem as applied to engine support personnel.

NRO review(s) completed.

SECRET

GROUP 1 clinical for automatic

d.wi.grad.ag. and Approved For Release 2004/12/15 : CIA-RDP71B00399R000600060018-9

declassification

25X1

SECRET

25X

SECRET

25X

Page 3

25X

3. Inertial Navigation System

The following information was extracted from the Contractor's Operations Plan.

- a. A 1 October 1967 approval is needed to insure:
- (1) Minimum level repair line beyond 19 November 1967.
- (2) Minimum spares to support the repair line.
- (3) Timely transfer of funds within existing subcontracts.
- b. Three options exist within the framework of present funding.*
 - (1) Option A. BLACK SHIELD can be supported through 17 December 1967 with:
 - (a) No transfer of funds between contracts.
 - (b) No spares delivery after 31 October 1967.
 - (c) The repair line maintained through 19 November 1967.
 - (2) Option B. BLACK SHIELD can be supported through 28 January 1968 with:
 - (a) A 1 October 1967 approval for limited spares delivery through 31 December 1967.
 - (b) The repair line maintained at present minimum support level through 31 December 1967.
 - (c) A 1 October 1967 approval for transfer of funds between contracts.

25X 25X

SECRET

Page 4

25X

- (3) Option C. BLACK SHIELD can be supported through 25 February 1968 with:
 - (a) A 1 October 1967 approval for transfer of funds between contracts.
 - (b) Maximum cannibalization.
 - (c) No repair line.
 - (d) No spares after 31 October 1967.
 - (e) Under Option C, no attempt at recovery could be made without experiencing a period of zero operational capability.
- * The present funding includes a fixed amount that has been set aside for INS close out.
 - a. Provides for two weeks packaging, crating, and technical services after the termination of BLACK SHIELD.

25X1

- 4. Engines The following is an analysis by the Contractor of engine support with the present level of funding:
 - a. BLACK SHIELD engine support through February 1968:
 - (1) At the existing flying hour rate per month
 - (2) No additional overhead
 - (3) Utilizing maximum field repair

25X1

25X1

SECRET

SECRET

Page 5

25X

- b. BLACK SHIELD parts and components support. the Feb
- (1) "Y" and "YJ-1" parts overhaul terminated 1 July 1967.
- (2) "Y" and "YJ-1" parts delivery terminates 31 October 1967.
 - (3) After October 1967; by maximum cannibalization.
- c. Examples of critical items requiring component repair line approval after 1 October 1967.
 - (1) Turbine Rotors balancing with new blades
 - (2) Engine nozzle control
 - (3) Afterburner fuel control

5. Spares

a. As of 15 September 1967, listed the following seven items as critical. The attached chart shows repair time and stocking levels.

- (1) Transducer AP-789-500
- (2) Actuator Bypass Door AS-1223-5
- (3) Actuator Spike AS1224-7
- (4) Pitot-Air Speed 4AQ-472-1
- (5) Drive Accessory-CSD 701732 & 695771
- (6) Coupler Heading BW-8KE66AC2
- (7) Gyro Platform BW-8KD9AC2

SECRET

25X

25X

25X

Attachments:

25X1 25X1

Next 2 Page(s) In Document Exempt